




If it were any easier, they would clean themselves



ST60

**Our slide top coolers** have easy-to-clean radius corners. We make it harder for ourselves to make it easier for you.


## Glastender



Front and rear interior panels extend around the side to eliminate corner seams

The stainless steel floor is formed into a pan with welded corners, eliminating floor corner seams

## The other guys



Non-radius side and floor corner seams that are difficult to clean

No stainless steel floor allows standing water to cause rusting

Expect more

*more flexibility*

more features